


10-32 Jack (Female) Connector, Cable Entry: Crimp  
Center Conductor: Solder Attachment for RG178, RG196 DC-2GHz

## 1032-2C50-G178B / H1



All dimensions are in mm [inch]

Tolerances according to DIN ISO 2768-mH

**Interface**

According to

N/A

**Electrical Data**

Impedance

50 Ω

Frequency

DC to 2 GHz

**Material And Plating**

Piece Parts	Material	Plating
Centre Contact	Phosphor Bronze	Gold plating, 3 pinch (Non-magnetic nickel-phosphorus underplating, 80 pinch)
Body	Brass	Gold plating, 3 pinch (Non-magnetic nickel-phosphorus underplating, 80 pinch)
Insulator	PTFE	
Gasket	Silicone Rubber	
Boot	Silicone Rubber	

**Mechanical Data**

Coupling Mechanisms	Screw-Lock
Mating Cycles	≥ 500
Centre Contact	Soldered
Cable Entry	Crimp

**Environmental Data**

Temperature Range	-55°C to +155°C
RoHS	compliant

**Suitable Cables**

RG178, RG196

**Packing**

Single or 100



10-32 Jack (Female) Connector, Cable Entry: Crimp  
Center Conductor: Solder Attachment for RG178, RG196 DC-2GHz

# 1032-2C50-G178B / H1

Connector Type:	1032-1C50-G178B/111 1032-2C50-G178B/H1	Inner Conductor Contact:	Soldered
Suitable Cable:	RG178, RG196	Outer Conductor Contact:	Crimped
Parts List of Connector:			
			Crimped Ferrule HEX. Crimp Size:  SW3.25 L.128 HEX.J
Assembly Steps:			
Picture	Process	Attention/Check	Tools Required
	Push ferrule "B" over the cable. Prepare the cable according to the diagram.	Do not damage center contact, dielectric and braid.	Blade Scissor
	Splay out braid and insert cable in outer conductor body "A" until it to stop. Solder center conductor according to the diagram.	Ensure that braid lies above crimp neck.	Solder Iron Solder Wire
	Slide ferrule "B" over braid and crimp.	Crimp as close to nut "B" as possible. Do not damage nut "B" and center conductor.	Crimp Tool: CT-L3 Crimp Insert: CI-L33JA